

Vibration Analysis Summary

Plant Name	Sanderson Farm
Location	Oakwood, TX
Date	July 9, 2024

ID#	Equipment		Note
HM#1	H/M Champion HM44-48		Extremely high mill vibration continued and increasing. Data shows unbalancing of rotors/hammers as well as looseness.
	Motor Toshiba 400HP/4P		High motor vibration continued and trending upward in vertical direction. Tighten all anchoring/bolts and inspect base for signs of cracks or damage. Check alignment as well.
HM#2	H/M Champion HM44-48		
	Motor Toshiba 400HP/4P		
HM#3	H/M Champion HM44-48		Mill vibration remains high and trending upward on non-drive end side of mill. H/M bearing noise (drive-end) continuing at unreliable levels. Defects, bearing retainer/inner-outer raceways such as pitting. Grease up bearings proper amount and prepare for bearings change out.
	Motor Toshiba 400HP/4P		
#1 Pellet Mill	CPM 7700-9000		
	Motor Toshiba 600HP/4P		
#2 Pellet Mill	CPM 7700-9000		Mill vibration has increased in the horizontal direction. Tighten all tie down bolts/anchoring.
	Motor Toshiba 600HP/4P		
#1 Cooler Fan	Industrial Air 540		
	Motor Baldor 200HP/4P		
#2 Cooler Fan	Industrial Air 540		
	Motor Toshiba 200HP/4P		High motor drive-end and non-drive end bearing noise continued and trending higher significantly on non-drive end side. Prepare for motor bearing change out.
Truck receiving Gear	Euro Drive MG3LHF09		
	Motor Reliance 200HP/4P		
Rail receiving Gear	Euro Drive MG3LHF09		
	Motor Reliance 200HP/4P		

Warning Flag Notation

Flag Type	Reliability Assessments
Normal	Reliable
Showed sign of problem(s)	Reliable, but concern(s) existed.
Progresses problem(s)	Not reliable for continuous operation.
Critical	Unsafe to operate

Next Inspection: In 6 months. January 2025



PdM Solutions of San Antonio, Inc

Vibration analysis, Thermal imaging, oil analysis ,laser alignment
Phone:(210)492-8363 Fax:(509)275-7676

Vibration Analysis Cover Sheet

1. Machinery Information.

Plant	Sanderson Farms	Location.	Oakwood, TX
Contract No.	Oakwood F/M Plant	Date	Jul 8,2024
Unit ID#	#1 Hammer Mill		
Model	Champion HM 44-48 S/N 442269-2014		
Drive	Direct Drive	Pump Speed	100%(1800RPM)
Motor BHP-RPM	400 HP-4P-VFD	Motor Manufacturer	Toshiba-TEFC TKKH 4F4400L180014
Motor Bearing-Drive	6320C3	Motor Bearing-Open	6320C3
Data Taken by	Scott Brown/PdM Solutions	Data Analyses by	Scott Brown/PdM Solutions
Service History			

2. Result

		Comment
Hammer Mill		Extremely high mill vibration continued and trending higher. Data showed balancing of rotor/hammers and looseness.
Motor		High motor vibration continued and trending higher.
Alignment		Alignment is likely off.

Warning Flag Notation

Flag Type	Reliability Assessments
Normal	Reliable
Showed a sign of problem(s)	Reliable, but concern(s) existed.
Progresses problem(s)	Not reliable for continuous operation.
Critical	Unsafe to operate

Inspection Note

- High hammer mill and motor vibration continued and trending higher.
- Data shows signs of balancing and mechanical looseness. Check for loose pillow block bolts and/or damage to the frame structure or bearing pedestal.
- Such high vibration can cause damage to outboard bearings on the mill.


3. Recommendation

- This H/M is not safe to operate. It will cause serious damages on motor and H/M.
- Immediately tighten all anchoring/nuts/bolts.
- Check/adjust alignment and coupling for damages such as shredding/twisting center piece.
- Check outboard pillow block bearings housing for looseness.
- Check balancing of mill rotor and make sure of the same qty of blades are on each rod.


4. Attachment

- Vibration last measurement report.
- Vibration trend data...motor/mill vibration.

5. Next Inspection. In (6) months, January 2025



Vibration trend data
#1 Hammer Mill and motor vibration continue trending higher. Data showed looseness and/or balancing of rotor/hammers. Check balancing of rotor cage and check hammers.(shape and qty of hammers on the shaft)
Check alignment of the motor and damages on coupling. Tighten all anchoring bolts/nuts.



PdM Solutions of San Antonio, Inc

Vibration analysis, Thermal imaging, oil analysis ,laser alignment
Phone:(210)492-8363 Fax:(509)275-7676

Vibration Analysis Cover Sheet

1. Machinery Information.

Plant	Sanderson Farms	Location.	Oakwood, TX
Contract No.	Oakwood F/M Plant	Date	July 9, 2024
Unit ID#	#3 Hammer Mill		
Model	Champion HM 44-48 S/N 442270-2014		
Drive	Direct Drive	Pump Speed	68%(1215RPM)
Motor BHP-RPM	400 HP-4P-VFD	Motor Manufacturer	Toshiba-TEFC TKKH 4F4400L180014
Motor Bearing-Drive	6320C3	Motor Bearing-Open	6320C3
Data Taken by	Scott Brown/PdM Solutions	Data Analyses by	Scott Brown/PdM Solutions
Service History			

2. Result

		Comment
Hammer Mill		Bearing noise continues at very high levels and trending even higher on non-drive end side of mill.
Motor		
Alignment		

Warning Flag Notation

Flag Type	Reliability Assessments
Normal	Reliable
Showed a sign of problem(s)	Reliable, but concern(s) existed.
Progresses problem(s)	Not reliable for continuous operation.
Critical	Unsafe to operate

Inspection Note

- High hammer mill vibration continued and increasing on non-drive end side of mill to non-reliable levels.
- Higher mill's drive end bearing noise is continued at critical levels.
- Hammer mills drive end bearings are not reliable for continuous operation.
- Mill bearings show signs of lack of lubrication.


3. Recommendation


- Schedule mills bearings change out.
- Check and clean off motor fan blades.
- Tighten all anchoring/nuts/bolts.
- Check coupling for damages center piece such as twisted or shredded.

4. Attachment

- Vibration last measurement report.
- Vibration trend data...Hammer mill bearing vibration

5. Next Inspection. In (6) months, January 2025





PdM Solutions of San Antonio, Inc

Vibration analysis, Thermal imaging, oil analysis ,laser alignment
Phone:(210)492-8363 Fax:(509)275-7676

Vibration Analysis Cover Sheet

1. Machinery Information.

Plant	Sanderson Farms	Location.	Oakwood, TX
Contract No.	Oakwood F/M plant	Date	July 9, 2024
Unit ID#	#2 Pellet Mill		
Model	CPM 7700-9000 S/N:		
Drive	Direct Drive	Pump Speed	1785 RPM
Motor BHP-RPM	600 HP-4P	Motor Manufacturer	Reliance
Motor Bearing-Drive	6320C3	Motor Bearing-Open	6320C3
Installation Note			
Data Taken by	Scott Brown/PdM Solutions	Data Analyses by	Scott Brown/PdM Solutions
Service History			

2. Result

		Comment
Pellet Mill	Yellow	Mill vibration increased in horizontal direction. Shows signs of looseness.
Motor	Green	

Warning Flag Notation

Flag Type	Reliability Assessments
Green	Normal
Yellow	Reliable
Yellow	Showed a sign of problem(s)
Pink	Reliable, but concern(s) existed.
Pink	Progresses problem(s)
Pink	Not reliable for continuous operation.
Red	Critical
Red	Unsafe to operate

Inspection Note

- Pellet mill vibration has increases in horizontal direction.
- Data shows signs of looseness.


3. Recommendation


- Tighten all bolts/anchoring to proper torque.
- Check vibration in 6 months.

4. Attachment

- Vibration last measurement report.
- Vibration trend data...mill vibration

5. Next Inspection. In (6) months, January 2025





PdM Solutions of San Antonio, Inc

Vibration analysis, Thermal imaging, oil analysis ,laser alignment
Phone:(210)492-8363 Fax:(509)275-7676

Vibration Analysis Cover Sheet

1. Machinery Information.

Plant	Sanderson Farms	Location.	Oakwood, TX
Contract No.	Oakwood F/M	Date	July 9, 2024
Unit ID#	#2 Cooling Fan		
Model	Industrial Air Technology Size 540 RTF-SW-14 505260		
Drive	V Belt Drive	Drive/Driven Speed	1775/1045 rpm
Motor BHP-RPM	200 HP4P/445T	Motor Manufacturer	Toshiba-TEFC
Motor Bearing-Drive	NU318	Motor Bearing-Open	6318C3
Note	Unit mounted on vibration isolation damper		
Data Taken by	Scott Brown/PdM Solutions	Data Analyses by	Hank/PdM Solutions
Service History			

2. Result

		Comment
Fan		
Motor		Higher motor bearing noise continued and increasing at a critical level on non-drive end side of motor. Prepare for motor change out.
Pillow Block Bearings		

Warning Flag Notation

Flag Type	Reliability Assessments	ANSI/AMCA 204-5 BV-3(Less than 400HP)
Normal	Reliable	0.25ips
Showed a sign of problem(s)	Reliable, but concern(s) existed.	0.5ips
Progresses problem(s)	Not reliable for continuous operation.	0.65ips
Critical	Unsafe to operate	0.7ips

Inspection Note

- High motor's drive end bearing noise continued.
- High motor's non- drive end bearing noised continued and increasing to critical level.
- Vibration continued to show signs of lack of lubrication.

3. Recommendation

- Grease up motor bearings recommended amount.
- Prepare to change out motor.

4. Attachment

- Vibration last measurement report
- Vibration trend data...motor bearing vibration

Next Inspection. In (6) months, **January 2025**

