

PdM Solutions of San Antonio, Inc

Vibration Analysis Summary


Plant Name	Sanderson Farm
Location	Oakwood, TX
Date	July 14, 2025

<u>ID#</u>	<u>Equipment</u>		<u>Note</u>
HM#1	H/M Champion HM44-48	Green	
	Motor Toshiba 400HP/4P	Green	
HM#2	H/M Champion HM44-48	Pink	High mill vibration observed. Data showed signs of looseness/unbalancing. Tighten all anchoring bolts/nuts/anchoring. Check mills drum/blades for possible unbalancing.
	Motor Toshiba 400HP/4P	Green	
HM#3	H/M Champion HM44-48	Pink	High hammer mill's pillow block bearing noise continued and trending higher. Data showed damages on raceways and/or retainer.se up the bearings. These bearings are not reliable for long term, continuous operation.
	Motor Toshiba 400HP/4P	Yellow	High motor bearings vibration continued and trending higher. Grease up bearings.
#1 Pellet Mill	CPM 7700-9000	Green	
	Motor Toshiba 600HP/4P	Green	
#2 Pellet Mill	CPM 7700-9000	Green	
	Motor Toshiba 600HP/4P	Green	
#1 Cooler Fan	Industrial Air 540	Green	
	Motor Baldor 200HP/4P	Green	
#2 Cooler Fan	Industrial Air 540	Green	
	Motor Toshiba 200HP/4P	Green	
Truck receiving Gear	Euro Drive MG3LHF09	Green	
	Motor Reliance 200HP/4P	Green	
Rail receiving Gear	Euro Drive MG3LHF09	Green	
	Motor Reliance 200HP/4P	Green	

Warning Flag Notation

Flag Type	Reliability Assessments
Green	Normal Reliable
Yellow	Showed sign of problem(s) Reliable, but concern(s) existed.
Pink	Progresses problem(s) Not reliable for continuous operation.
Red	Critical Unsafe to operate

Next Inspection: In 6 months. January 2026



PdM Solutions of San Antonio, Inc

Vibration analysis, Thermal imaging, oil analysis ,laser alignment
Phone:(210)492-8363 Fax:(509)275-7676

Vibration Analysis Cover Sheet

1. Machinery Information.

Plant	Sanderson Farms	Location.	Oakwood, TX
Contract No.	Oakwood F/M Plant	Date	July 14, 2025
Unit ID#	#2 Hammer Mill		
Model	Champion HM 44-48 S/N 442269-2014		
Drive	Direct Drive	Pump Speed	100% (1800RPM)
Motor BHP-RPM	400 HP-4P-VFD	Motor Manufacturer	Toshiba-TEFC TKKH 4F4400L180014
Motor Bearing-Drive	6320C3	Motor Bearing-Open	6320C3
Data Taken by	Scott Brown/PdM Solutions	Data Analyses by	Scott Brown/PdM Solutions
Service History			

2. Result

		Comment
Hammer Mill		High hammer mill vibration observed. Data showed signs of looseness/unbalancing at the base of the mill and unbalancing of mill's blades.
Motor		
Alignment		

Warning Flag Notation

Flag Type	Reliability Assessments
	Normal
	Reliable
	Showed a sign of problem(s)
	Reliable, but concern(s) existed.
	Progresses problem(s)
	Not reliable for continuous operation.
	Critical
	Unsafe to operate

Inspection Note


3. Recommendation

- Tighten all anchoring/nuts/bolts.
- Check the mill's rotors and blades for possible unbalancing source.

4. Attachment

- Vibration last measurement report.
- Vibration trend data...Mill vibration.

5. Next Inspection. In (6) months, January 2026





PdM Solutions of San Antonio, Inc

Vibration analysis, Thermal imaging, oil analysis ,laser alignment
Phone:(210)492-8363 Fax:(509)275-7676

Vibration Analysis Cover Sheet

1. Machinery Information.

Plant	Sanderson Farms	Location.	Oakwood, TX
Contract No.	Oakwood F/M Plant	Date	July 14, 2025
Unit ID#	#3 Hammer Mill		
Model	Champion HM 44-48 S/N 442270-2014		
Drive	Direct Drive	Mill Speed	68%(1215RPM)
Motor BHP-RPM	400 HP-4P-VFD	Motor Manufacturer	Toshiba-TEFC TKKH 4F4400L180014
Motor Bearing-Drive	6320C3	Motor Bearing-Open	6320C3
Data Taken by	Scott Brown/PdM Solutions	Data Analyses by	Scott Brown/PdM Solutions
Service History			

2. Result

		Comment
Hammer Mill		Higher bearing noise continued and trending higher. Data showed bearing damages such as pitting on the raceways and/or worn out retainer.
Motor		High mill bearings vibration continued. Data showed signs of lack of lubrication and/or slight damage on bearing raceways.
Alignment		

Warning Flag Notation

Flag Type	Reliability Assessments
	Normal
	Reliable
	Showed a sign of problem(s)
	Reliable, but concern(s) existed.
	Progresses problem(s)
	Not reliable for continuous operation.
	Critical
	Unsafe to operate

Inspection Note

- High hammer mill's drive end bearing noise continued and trending higher.
- Mill bearings show signs of lack of lubrication.
- Mill motor bearings showed signs of lack of lubrication.

3. Recommendation

- Grease up the hammer mills bearings.
- Hammer mills drive end bearings are not reliable for continuous operation.
- Grease up motor bearings.

4. Attachment

- Vibration last measurement report.
- Vibration trend data...HM drive end bearing noise

5. Next Inspection. In (6) months, **January 2026**

