



Home of PdM services Vibration Analysis,Precision laser shaft alignment, Thermographic Inspection,Oil analysis P.O.Box 160758 San Antonio TX 78280 (210)492-8363

Thermographic Exception Report

Area/Item I.D.	CC193/Engine Room #2
Description	Main Panel D Compressor 3
Severity Assesment	Level-II
Detail	Knife fuse socket overheating.
Action Recommended	Clean fuse knife sockets.





Measurements		
Bx1		
Max	209.4 °F	
Avg Min	151.4 °F	
Min	95.2 °F	